
First Meeting of the Passaic River Basin Flood Advisory Commission



DEP Support to the Passaic River Basin Flood Advisory Commission

Natural and Historic Resources Amy Cradic, Assistant Commissioner

> Office of Engineering and Construction, David Rosenblatt, Administrator



Dam Permits and Safety Inspections
Flood Mitigation
Floodplain Mapping
Community Assistance with FEMA Grant



Passaic River Basin









Figure courtesy of USACE NY District




PASSAIC RIVER BASIN FLOOD ADVISORY COMMISSION MAP - LOWER WAYNE TWP






Screen capture of National Weather Service map of total observed precipitation for for the 7-day period ending March 16, 2010, at 0800 hours EDT. (from National Weather Service, 2010)





Screen capture of National Oceanic and Atmospheric Administration map of snow snow cover, in inches of water equivalent, on **February 27, 2010**. (from National National Weather Service, 2010)





Screen capture of National Oceanic and Atmospheric Administration map of snow snow cover in inches of water equivalent on **March 12, 2010** (from National Weather Service, 2010)





Photograph of flooding at the stage-only gaging station on the Ramapo River at Dawes Dawes Highway at Pompton, NJ (U.S.Geological Survey station 01388100), at peak stage on March 14, 2010, at 1:30 PM EDT. (Photograph by John Trainor, U.S. Geological Survey)



March 2010 Storm Comparison

Ramapo River near Mahwah (120 sq mi)

3/14/2010 5th highest peak of record Q = 11,500 cfs, 40-yr event

4/5/1984 historic peak of record Q = 15,500 cfs, 95-yr event

Pompton River at Pompton Plains (355 sq mi)

3/14/2010 3rd highest peak of record Q = 20,400 cfs, 40-yr event

10/10/1903 historic peak of record Q = 28,300 cfs, >100-yr event

Rockaway River above reservoir at Boonton (116 sq mi)

3/14/2010 5th highest peak of record Q = 4,350 cfs, 20-yr event

4/5/1984 historic peak of record Q = 5,590 cfs, 50-yr event

Passaic River at Pine Brook (349 sq mi)

3/16/2010 new peak of record Q = 9,100 cfs, 60-yr event

4/5/1984 previous peak of record Q = 8,000 cfs, 50-yr event

Passaic River at Little Falls (762 sq mi)

3/16/2010 storm peak Q = 15,800 cfs, 20 -yr event

10/10/1903 historic peak of record Q = 31,700 cfs, >100-yr event



Conclusions from "The Passaic Flood of 1903" USGS Report

- 1. Great floods in the Passaic Basin arise only after a specially violent precipitation.
- 2. Under present conditions floods may be expected at frequent intervals.
- 3. A part of the damage along the lower valley is the result of encroachments on the part of individuals and public and private corporations.
- 4. The channel in the lower valley may be improved at certain points by straightening it and judiciously making cut-offs.
- 5. Without the construction of numerous levees the lower valley channel can not be made to carry great flood waters without damage.
- 6. Immunity from floods can be effected only by the construction of catchment reservoirs in the highlands or levees in the lowlands.
- 7. Levee construction would involve more damage than is now caused by floods, and the cost cost thereof would be prohibitive.
- 8. Flood catchment reservoirs may be constructed economically and provide storage to compensate for the dry-season flow, thereby maintaining water power at Paterson, Passaic, and other points, and providing for future municipal water supply.